



SCUBAPRO MK 25-MK 20 First Stages




Trouble Shooting Guide

Symptom	Correction	Tools Needed

SCUBAPRO MK 25-MK 20 First Stages

Trouble Shooting Guide

Symptom	Correction		Tools Needed	
Low IP at 300 psi	Adjust IP with adjusting screw	Replace spring or shim	Pneumatic adjusting tool	5/32” hex
				

Initial IP creep on gauge	New seat: Cycle regulator 20 – 25 times	Pneumatic adjustment tool
		

Continuous IP creep on gauge	Replace seat	Replace Piston	Various	
